## 06/03/03 : CIA-RDP82-00457R003800270009-6 Approved For

	CLASSIFICATION	SECRET/CORTEOL/US OF ICA IS ONLY	
COUNTRY Soviet	Zone of German	REPORT	
TOPIC DESSAU	lirfield	. 2	25X1
	٠.		
EVALUATION	25X1	PLACE OBTAINED	All controls have been part or the part of
DATE OF CONTENT		25X1 25X1	
DATE OBTAINED		DATE PREPARED 1 November 1949	10
REFERÊNCES	25X1	<u> </u>	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
PAGES 2	ENCLOSURES (NO.	& TYPE) 1 diagram	<i>)</i> (
REMARKS			The state of the s
The relative parties and the should be a second of the second second second second second second second second		RETURN TO CIA LIBRARY	eri eri mani mandan ng managamangan sagayanang
			46 virti kiralinastari. Iyi galahki kilagi kemulusulgu kilolog
	The second secon		A Printer of the Land of the L
			,


- Improvements were being made at the DESSAU (M 52/E 08) airfield. About two hundred workers were engaged in recondition-25X1 ing and extending the texiway.\* Ditches, 10 to 16 feet wide and 10 to 13 feet deep, were being excavated in the northern section of the airfield, starting almost in the middle of the field, and extending toward the runway. \* Two railroad tank cars were standing on the spur track. Obstacle lights were in operation at night. The boundary lights were destroyed. No radio station was observed.
  - Two biplanes and thirty-six single-engine fighters were parked on the castern edge of the field. Of these fighters, 24 had red and 3 blue propeller hubs. Description of the 27 fighters: \*\*

Radial engine, three-bladed propeller, large propeller hub, trapezoidal wings slightly dihedral. Straight trailing edge of elevator assembly, triangular rudder assembly with roundedoff trailing edge, landing gear and tail wheel retractable, the latter covered with sheet metal. Letached single-seat cockpit with rear section fairing into fuselage. Device, similar to a searchlight, apparently a Revi, forward of cockpit (see Annex). Cut, similar to machine gun or cannon aperture, engine cowling, static tube at right wing, antenna leading to rudder assembly, stubby and clumsy fuschage. Bomb rack or extra tank at bottom of fuschage, almost at center of gravity (suspension hook and side brace). Radiator at bottom of fuschage.

edge of wings, 25X1 Some planes had two diagonal red stripes on a yellow field on the rudder assembly.

There were six more aircraft with two-seat cockpits, no bomb rack under fuselage, radiator under fuselage in line with con 25X1 red propeller hube

aree more aircraft of the same type had a somewhat Lower landing gear and two-bladed propellers.



25X1

25X1

25X1

4.	Highty to a hundred air force officers arrived by truck and
	bus from ALTEN (3 52/E 06) at 12:30 p.m. There was flying with 18 aircraft. These single-scat fighters took off in
	elements of two from the sodded landing field and later
	landed individually. The two-seat fighters individually circled the airfield.

25X1 Comment:

\* a. The construction work on the taxiway (probably extension in accordance with lengthening of the runway) was confirmed.

The excavation of deep ditches in the northern section of the airfield was reported for the first time. Fuel containers are possibly to be installed there.

\*\* b. Report confirms observation on 21 September 1949 of the occupation of the airfield by a fighter unit. According to the description of the aircraft, the unit is equipped with IA-9s.

1 Annex: Partial Side View of righter Aircraft Observed at the DESSAU Airfield.

25X1

25X1


CONFIDENTIAL

CECHAT-CONTROL/ US OFF ICIALS ONLY

## CONFIDENTIAL

SHORET/CONTROL - U.S. OFFICIALS ONLY 25X1

Partial Side View of Fightor Aircraft Observed at the Dessau Airfield



CONFIDENTIAL

-SECRET/CONTROL - U.S. OFFICIALS ONLY